TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										**NA**			
EPA Site Specific Trigger Levels										**70**			
ASBESTOS-ST1-8/3/06	030624860-0001	Southwest Area (sidewalk bridge level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST2-8/3/06	030624860-0002	Southeast Area (sidewalk bridge level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST4-8/3/06	030624860-0003	Northwest Area (street-level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST5-8/3/06	030624860-0004	Firehouse #10 (roof level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST6-8/3/06	030624865-0001	Southwest Area (roof level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST8-8/3/06	030624865-0002	Northeast Area (roof level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST9-8/3/06	030624865-0003	Northwest Area (roof level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST10-8/3/06	030624860-0005	North Side Sidewalk Bridge	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST11-8/3/06	030624860-0006	90 Trinity Place (roof level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST12-8/3/06	030624860-0007	110 Greenwich Street (roof level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST13-8/3/06	030624860-0008	Marriott Hotel, 38th Floor (roof level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST14-8/3/06	030624860-0009	West Face - South end at corner (scaffolding level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST15-8/3/06	030624860-0010	South Face - East end at corner (scaffolding level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST16-8/3/06	030624860-0011	East Face - North end at corner (scaffolding level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST17-8/3/06	030624860-0012	North Face - West end at corner (scaffolding level)	8/3/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/5/06	< 13.00	No	No	
ASBESTOS-ST1-8/4/06	030625185-0001	Southwest Area (sidewalk bridge level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST2-8/4/06	030625185-0002	Southeast Area (sidewalk bridge level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST4-8/4/06	030625185-0003	Northwest Area (street-level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST5-8/4/06	030625185-0004	Firehouse #10 (roof level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST6-8/4/06	030625184-0001	Southwest Area (roof level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST7-8/4/06	030625184-0002	Southeast Area (roof level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST8-8/4/06	030625184-0003	Northeast Area (roof level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST9-8/4/06	030625184-0004	Northwest Area (roof level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST10-8/4/06	030625185-0005	North Side Sidewalk Bridge	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST11-8/4/06	030625185-0006	90 Trinity Place (roof level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST12-8/4/06	030625185-0007	110 Greenwich Street (roof level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST13-8/4/06	030625185-0008	Marriott Hotel, 38th Floor (roof level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST14-8/4/06	030625185-0009	West Face - South end at corner (scaffolding level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST15-8/4/06	030625185-0010	South Face - East end at corner (scaffolding level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST16-8/4/06	030625185-0011	East Face - North end at corner (scaffolding level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST17-8/4/06	030625185-0012	North Face - West end at corner (scaffolding level)	8/4/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST1-8/5/06	030625182-0001	Southwest Area (sidewalk bridge level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST2-8/5/06	030625182-0002	Southeast Area (sidewalk bridge level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST4-8/5/06	030625182-0003	Northwest Area (street-level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST5-8/5/06	030625182-0004	Firehouse #10 (roof level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST6-8/5/06	030625183-0001	Southwest Area (roof level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST7-8/5/06	030625183-0002	Southeast Area (roof level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST8-8/5/06	030625183-0003	Northeast Area (roof level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST9-8/5/06	030625183-0004	Northwest Area (roof level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST10-8/5/06	030625182-0005	North Side Sidewalk Bridge	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	13.00	No	No	
ASBESTOS-ST11-8/5/06	030625182-0006	90 Trinity Place (roof level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST12-8/5/06	030625182-0007	110 Greenwich Street (roof level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST13-8/5/06	030625182-0008	Marriott Hotel, 38th Floor (roof level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST14-8/5/06	030625182-0009	West Face - South end at corner (scaffolding level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST15-8/5/06	030625182-0010	South Face - East end at corner (scaffolding level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST16-8/5/06	030625182-0011	East Face - North end at corner (scaffolding level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST17-8/5/06	030625182-0012	North Face - West end at corner (scaffolding level)	8/5/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST1-8/6/06	030625189-0001	Southwest Area (sidewalk bridge level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST2-8/6/06	030625189-0002	Southeast Area (sidewalk bridge level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST4-8/6/06	030625189-0003	Northwest Area (street-level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST5-8/6/06	030625189-0004	Firehouse #10 (roof level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST6-8/6/06	030625187-0001	Southwest Area (roof level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST7-8/6/06	030625187-0002	Southeast Area (roof level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST8-8/6/06	030625187-0003	Northeast Area (roof level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST9-8/6/06	030625187-0004	Northwest Area (roof level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST10-8/6/06	030625189-0005	North Side Sidewalk Bridge	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST11-8/6/06	030625189-0006	90 Trinity Place (roof level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST12-8/6/06	030625189-0007	110 Greenwich Street (roof level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST13-8/6/06	030625189-0008	Marriott Hotel, 38th Floor (roof level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST14-8/6/06	030625189-0009	West Face - South end at corner (scaffolding level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST15-8/6/06	030625189-0010	South Face - East end at corner (scaffolding level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST16-8/6/06	030625189-0011	East Face - North end at corner (scaffolding level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	
ASBESTOS-ST17-8/6/06	030625189-0012	North Face - West end at corner (scaffolding level)	8/6/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/06	< 13.00	No	No	

Note:
1. Asbestos sample at Station 7 (Southeast Area [roof level]) on August 3, 2006 was not available for analysis on account of media damage.