TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										**NA**			
EPA Site Specific Trigger Levels										**70**			
ASBESTOS-ST1-8/10/06	030625682-0001	Southwest Area (sidewalk bridge level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST2-8/10/06	030625682-0002	Southeast Area (sidewalk bridge level)	8/10/06	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST4-8/10/06	030625682-0003	Northwest Area (street-level)	8/10/06	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST5-8/10/06	030625682-0004	Firehouse #10 (roof level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST6-8/10/06	030625887-0001	Southwest Area (roof level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST7-8/10/06	030625887-0002	Southeast Area (roof level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST8-8/10/06	030625887-0003	Northeast Area (roof level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST9-8/10/06	030625887-0004	Northwest Area (roof level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST10-8/10/06	030625682-0005	North Side Sidewalk Bridge	8/10/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST11-8/10/06	030625682-0006	90 Trinity Place (roof level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST12-8/10/06	030625682-0007	110 Greenwich Street (roof level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST13-8/10/06	030625682-0008	Marriott Hotel, 38th Floor (roof level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST15-8/10/06	030625682-0009	South Face - East end at corner (scaffolding level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST16-8/10/06	030625682-0010	East Face - North end at corner (scaffolding level)	8/10/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST17-8/10/06	030625682-0011	North Face - West end at corner (scaffolding level)	8/10/06	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/11/06	< 13.00	No	No	
ASBESTOS-ST1-8/11/06	030626205-0001	Southwest Area (sidewalk bridge level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST2-8/11/06	030626205-0002	Southeast Area (sidewalk bridge level)	8/11/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST4-8/11/06	030626205-0003	Northwest Area (street-level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST5-8/11/06	030626205-0004	Firehouse #10 (roof level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST6-8/11/06	030626208-0001	Southwest Area (roof level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST7-8/11/06	030626208-0002	Southeast Area (roof level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST8-8/11/06	030626208-0003	Northeast Area (roof level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST9-8/11/06	030626208-0004	Northwest Area (roof level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST10-8/11/06	030626205-0005	North Side Sidewalk Bridge	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST11-8/11/06	030626205-0006	90 Trinity Place (roof level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST12-8/11/06	030626205-0007	110 Greenwich Street (roof level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST13-8/11/06	030626205-0008	Marriott Hotel, 38th Floor (roof level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST14-8/11/06	030626205-0009	West Face - South end at corner (scaffolding level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST15-8/11/06	030626205-0010	South Face - East end at corner (scaffolding level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST16-8/11/06	030626205-0011	East Face - North end at corner (scaffolding level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST17-8/11/06	030626205-0012	North Face - West end at corner (scaffolding level)	8/11/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST1-8/12/06	030626209-0001	Southwest Area (sidewalk bridge level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST2-8/12/06	030626209-0002	Southeast Area (sidewalk bridge level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST4-8/12/06	030626209-0003	Northwest Area (street-level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST5-8/12/06	030626209-0004	Firehouse #10 (roof level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST6-8/12/06	030626211-0001	Southwest Area (roof level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST7-8/12/06	030626211-0002	Southeast Area (roof level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST8-8/12/06	030626211-0003	Northeast Area (roof level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST9-8/12/06	030626211-0004	Northwest Area (roof level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST10-8/12/06	030626209-0005	North Side Sidewalk Bridge	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST11-8/12/06	030626209-0006	90 Trinity Place (roof level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST12-8/12/06	030626209-0007	110 Greenwich Street (roof level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST13-8/12/06	030626209-0008	Marriott Hotel, 38th Floor (roof level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST14-8/12/06	030626209-0009	West Face - South end at corner (scaffolding level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST15-8/12/06	030626209-0010	South Face - East end at corner (scaffolding level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST16-8/12/06	030626209-0011	East Face - North end at corner (scaffolding level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST17-8/12/06	030626209-0012	North Face - West end at corner (scaffolding level)	8/12/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST1-8/13/06	030626213-0001	Southwest Area (sidewalk bridge level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST2-8/13/06	030626213-0002	Southeast Area (sidewalk bridge level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST4-8/13/06	030626213-0003	Northwest Area (street-level)	8/13/06	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST5-8/13/06	030626213-0004	Firehouse #10 (roof level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST6-8/13/06	030626215-0001	Southwest Area (roof level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST7-8/13/06	030626215-0002	Southeast Area (roof level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST8-8/13/06	030626215-0003	Northeast Area (roof level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST9-8/13/06	030626215-0004	Northwest Area (roof level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST10-8/13/06	030626213-0005	North Side Sidewalk Bridge	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST11-8/13/06	030626213-0006	90 Trinity Place (roof level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST12-8/13/06	030626213-0007	110 Greenwich Street (roof level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST13-8/13/06	030626213-0008	Marriott Hotel, 38th Floor (roof level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST14-8/13/06	030626213-0009	West Face - South end at corner (scaffolding level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST15-8/13/06	030626213-0010	South Face - East end at corner (scaffolding level)	8/13/06	1	2.880	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST16-8/13/06	030626213-0011	East Face - North end at corner (scaffolding level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	
ASBESTOS-ST17-8/13/06	030626213-0012	North Face - West end at corner (scaffolding level)	8/13/06	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/14/06	< 13.00	No	No	

Note:
1. Asbestos sample at Station 14 (West Face - South end at corner [scaffolding level]) on August 10, 2006 was not available for analysis on account of pump failure.