TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m^3)	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos PCME Concentration (f/cm3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels										**0.0009**			
EPA Site Specific Trigger Levels										**NA**			
ASBESTOS -ST1-9/1/06	030628987-0001	Southwest Area (sidewalk bridge level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST2-9/1/06	030628987-0002	Southeast Area (sidewalk bridge level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST4-9/1/06	030628987-0003	Northwest Area (street-level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST5-9/1/06	030628987-0004	Firehouse #10 (roof level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST6-9/1/2006	030628988-0001	Southwest Area (roof level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST7-9/1/2006	030628988-0002	Southeast Area (roof level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST8-9/1/2006	030628988-0003	Northeast Area (roof level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST9-9/1/2006	030628988-0004	Northwest Area (roof level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST10-9/1/06	030628987-0005	North Side Sidewalk Bridge	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST100-9/1/06	030628987-0013	Station 10 Field Duplicate	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST11-9/1/06	030628987-0006	90 Trinity Place (roof level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST12-9/1/06	030628987-0007	110 Greenwich Street (roof level)	9/1/06	1	3.090	Asbestos	PCME	EMSL	9/5/06	< 0.00080	No	No	
ASBESTOS -ST13-9/1/06	030628987-0008	Marriott Hotel, 38th Floor (roof level)	9/1/06	1	3.060	Asbestos	PCME	EMSL	9/5/06	< 0.00081	No	No	
ASBESTOS -ST14-9/1/06	030628987-0009	West Face - South end at corner (scaffolding level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST15-9/1/06	030628987-0010	South Face - East end at corner (scaffolding level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST16-9/1/06	030628987-0011	East Face - North end at corner (scaffolding level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS -ST17-9/1/06	030628987-0012	North Face - West end at corner (scaffolding level)	9/1/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST1-9/2/06	030629018-0001	Southwest Area (sidewalk bridge level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST2-9/2/06	030629018-0002	Southeast Area (sidewalk bridge level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST4-9/2/06	030629018-0003	Northwest Area (street-level)	9/2/06	1	3.150	Asbestos	PCME	EMSL	9/5/06	< 0.00078	No	No	
ASBESTOS-ST5-9/2/06	030629018-0004	Firehouse #10 (roof level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST6-9/2/06	030629037-0001	Southwest Area (roof level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST7-9/2/06	030629037-0002	Southeast Area (roof level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST8-9/2/06	030629037-0003	Northeast Area (roof level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST9-9/2/06	030629037-0004	Northwest Area (roof level)	9/2/06	1	3.090	Asbestos	PCME	EMSL	9/5/06	< 0.00080	No	No	
ASBESTOS-ST10-9/2/06	030629018-0005	North Side Sidewalk Bridge	9/2/06	1	3.090	Asbestos	PCME	EMSL	9/5/06	< 0.00080	No	No	
ASBESTOS-ST11-9/2/06	030629018-0006	90 Trinity Place (roof level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST12-9/2/06	030629018-0007	110 Greenwich Street (roof level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST13-9/2/06	030629018-0008	Marriott Hotel, 38th Floor (roof level)	9/2/06	1	3.090	Asbestos	PCME	EMSL	9/5/06	< 0.00080	No	No	
ASBESTOS-ST14-9/2/06	030629018-0009	West Face - South end at corner (scaffolding level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST15-9/2/06	030629018-0010	South Face - East end at corner (scaffolding level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST16-9/2/06	030629018-0011	East Face - North end at corner (scaffolding level)	9/2/06	1	2.960	Asbestos	PCME	EMSL	9/5/06	< 0.00083	No	No	
ASBESTOS-ST17-9/2/06	030629018-0012	North Face - West end at corner (scaffolding level)	9/2/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST1-9/3/06	030628991-0001	Southwest Area (sidewalk bridge level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST2-9/3/06	030628991-0002	Southeast Area (sidewalk bridge level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST4-9/3/06	030628991-0003	Northwest Area (street-level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST5-9/3/06	030628991-0004	Firehouse #10 (roof level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST6-9/3/06	030628992-0001	Southwest Area (roof level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST7-9/3/06	030628992-0002	Southeast Area (roof level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST8-9/3/06	030628992-0003	Northeast Area (roof level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST9-9/3/06	030628992-0004	Northwest Area (roof level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST10-9/3/06	030628991-0005	North Side Sidewalk Bridge	9/3/06	1	3.090	Asbestos	PCME	EMSL	9/5/06	< 0.00080	No	No	
ASBESTOS-ST11-9/3/06	030628991-0006	90 Trinity Place (roof level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST12-9/3/06	030628991-0007	110 Greenwich Street (roof level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST13-9/3/06	030628991-0008	Marriott Hotel, 38th Floor (roof level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST14-9/3/06	030628991-0009	West Face - South end at corner (scaffolding level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST15-9/3/06	030628991-0010	South Face - East end at corner (scaffolding level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST16-9/3/06	030628991-0011	East Face - North end at corner (scaffolding level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST17-9/3/06	030628991-0012	North Face - West end at corner (scaffolding level)	9/3/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST1-9/4/06	030628993-0001	Southwest Area (sidewalk bridge level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST2-9/4/06	030628993-0002	Southeast Area (sidewalk bridge level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST4-9/4/06	030628993-0003	Northwest Area (street-level)	9/4/06	1	3.210	Asbestos	PCME	EMSL	9/5/06	< 0.00077	No	No	
ASBESTOS-ST5-9/4/06	030628993-0004	Firehouse #10 (roof level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST6-9/4/06	030628994-0001	Southwest Area (roof level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST7-9/4/06	030628994-0002	Southeast Area (roof level)	9/4/06	1	3.040	Asbestos	PCME	EMSL	9/5/06	< 0.00081	No	No	
ASBESTOS-ST8-9/4/06	030628994-0003	Northeast Area (roof level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST9-9/4/06	030628994-0004	Northwest Area (roof level)	9/4/06	1	3.010	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST10-9/4/06	030628993-0005	North Side Sidewalk Bridge	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST11-9/4/06	030628993-0006	90 Trinity Place (roof level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST12-9/4/06	030628993-0007	110 Greenwich Street (roof level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST13-9/4/06	030628993-0008	Marriott Hotel, 38th Floor (roof level)	9/4/06	1	2.960	Asbestos	PCME	EMSL	9/5/06	< 0.00083	No	No	
ASBESTOS-ST14-9/4/06	030628993-0009	West Face - South end at corner (scaffolding level)	9/4/06	1	2.900	Asbestos	PCME	EMSL	9/5/06	< 0.00085	No	No	
ASBESTOS-ST15-9/4/06	030628993-0010	South Face - East end at corner (scaffolding level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST16-9/4/06	030628993-0011	East Face - North end at corner (scaffolding level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST17-9/4/06	030628993-0012	North Face - West end at corner (scaffolding level)	9/4/06	1	3.020	Asbestos	PCME	EMSL	9/5/06	< 0.00082	No	No	
ASBESTOS-ST1-9/5/06	030629149-0001	Southwest Area (sidewalk bridge level)	9/5/06	1	3.090	Asbestos	PCME	EMSL	9/6/06	< 0.00080	No	No	
ASBESTOS-ST2-9/5/06	030629149-0002	Southeast Area (sidewalk bridge level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	
ASBESTOS-ST4-9/5/06	030629149-0003	Northwest Area (street-level)	9/5/06	1	3.150	Asbestos	PCME	EMSL	9/6/06	< 0.00078	No	No	
ASBESTOS-ST5-9/5/06	030629149-0004	Firehouse #10 (roof level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	0.00082	No	No	
ASBESTOS-ST6-9/5/06	030629160-0001	Southwest Area (roof level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	
ASBESTOS-ST7-9/5/06	030629160-0002	Southeast Area (roof level)	9/5/06	1	3.060	Asbestos	PCME	EMSL	9/6/06	< 0.00081	No	No	
ASBESTOS-ST8-9/5/06	030629160-0003	Northeast Area (roof level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	
ASBESTOS-ST9-9/5/06	030629160-0004	Northwest Area (roof level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	
ASBESTOS-ST10-9/5/06	030629149-0005	North Side Sidewalk Bridge	9/5/06	1	3.090	Asbestos	PCME	EMSL	9/6/06	< 0.00080	No	No	
ASBESTOS-ST11-9/5/06	030629149-0006	90 Trinity Place (roof level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	
ASBESTOS-ST12-9/5/06	030629149-0007	110 Greenwich Street (roof level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	
ASBESTOS-ST13-9/5/06	030629149-0008	Marriott Hotel, 38th Floor (roof level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	
ASBESTOS-ST14-9/5/06	030629149-0009	West Face - South end at corner (scaffolding level)	9/5/06	1	3.090	Asbestos	PCME	EMSL	9/6/06	< 0.00080	No	No	
ASBESTOS-ST15-9/5/06	030629149-0010	South Face - East end at corner (scaffolding level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	
ASBESTOS-ST16-9/5/06	030629149-0011	East Face - North end at corner (scaffolding level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	
ASBESTOS-ST17-9/5/06	030629149-0012	North Face - West end at corner (scaffolding level)	9/5/06	1	3.020	Asbestos	PCME	EMSL	9/6/06	< 0.00082	No	No	