REVISIONS		
NO.	DATE	DESCRIPTION
A	10-25-71	REVISED GLASS THICKNESS • REVISED CURB DETN. @ MULLION ANCHORAGE AT 5TH & 33RD FLRS • REVISED WINDOW & SPANDREL HEIGHTS • ADDED CLARIFYING NOTES & REFERENCES •
B	11-11-71	REVISED GLASS THICKNESS @ 2ND FLR. SPANDREL FROM 5/8" TO 7/8" AND AT VISION PANEL 34TH FLR. FROM 5/8" TO 1/4". ADDED CLARIFYING NOTES TO SECTIONS 2 & 3.
C	6-12-72	REVISED CONV. UNITS ON 33, 35, 36, 37 FLRS
D	9-12-72	ADDED FIBERGLASS FIRE STOP
E	10-23-73	ELIMINATED ALL THRU BLIND POCKETS

B.T.CO.	1	12-13-77	PC
B.T.	3	11-4-74	PC 31148
F/W	2	7-10-74	PC 30666
F/W	1	4-22-74	PC 30143
F/W	2	2-4-74	PC 29226
F/W	4	1-29-74	PC 29215
F/W	1	1-20-74	PC 29300
F/W	1	12-18-73	PC 28296
LOUVER MAN.	1	11-14-73	PC 27649
F/W	2	11-12-73	PC 27647
F/W	101	10-30-73	PC 28169
F/W	10+	10-23-73	PC 28157
REVISION	E	10-23-73	
G.H.&K.	1	10-9-73	PC 27626
DESIGN	1	8-30-73	PC 27303
HKLEES.	1	6-11-73	PC 27142
F/W	6	5-7-73	PC 23781
B.T.Co.	24	4-19-73	PC 26139
F/W	31	4-12-73	PC 26115
KNEELAND	1	3-15-73	PC 25111
F/W	10	2-8-73	PC 25127
F/W	10	12-19-72	PC 19895
F/W	20	11-17-72	PC 24210
F/W	10	10-26-72	PC 23928
F/W	2	10-18-72	PC 23074
F/W	2	9-26-72	PC 22975
F/W	10	9-21-72	PC 22891
BLDG DEPT.	2	9-12-72	PC 22976
REVISION	D	9-12-72	
F/W	74	9-7-72	PC 22972
ISSUED TO	NO.	DATE	PKG. NO.

BANKERS TRUST PLAZA

A FISHER BROTHERS PROJECT

GREENWICH AND LIBERTY ST. N.Y. N.Y.

SHREVE, LAMB & HARMON ASSOCIATES P.C.
ARCHITECTS
475 PARK AVENUE SOUTH N.Y. N.Y. 10016

PETERSON AND BRICKBAUER
ASSOCIATED ARCHITECTS
919 THIRD AVENUE N.Y. N.Y. 10022

THE OFFICE OF JAMES RUDERMAN
STRUCTURAL ENGINEERS
515 MADISON AVENUE N.Y. N.Y. 10022

J A R O S , B A U M & B O L L E S
MECH. & ELEC. ENGINEERS
345 PARK AVENUE N.Y. N.Y. 10022

WALL SECTIONS
SHEET No 1

PROJECT NUMBER 7101

DRAWING NUMBER A50

DATE SEP 21, 1971

SCALE 1/2" = 1'-0"

4 UPPER TOWER MAIN ROOF

3 UPPER TOWER TYPICAL

2 LOWER TOWER TYPICAL

1 LOWER TOWER TYPICAL

NOTE: FLOORS SHOWN ON THIS DWG. ARE CONSTRUCTION FLOORS.