

TRC Field Sample No.	Station Location	Collection Start Date	Collection Time (minutes)	Analyte	Analytical Method	Instrument	Particulate PM10 (ug/m3)	Exceeds Target Air Quality Levels	Exceeds EPA Site Specific Trigger Levels	Comments
Target Air Quality Levels							150			
EPA Site Specific Trigger Levels							150			
PM10-ST1-6/28/2006	Southwest Area (sidewalk bridge level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST2-6/28/2006	Southeast Area (sidewalk bridge level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST4-6/28/2006	Northwest Area (street-level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	26	No	No	
PM10-ST5-6/28/2006	Firehouse #10 (roof level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST10-6/28/2006	North Side Sidewalk Bridge	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	29	No	No	
PM10-ST100-6/28/2006	Station 10 Field Duplicate	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST11-6/28/2006	90 Trinity Place (roof level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	25	No	No	
PM10-ST12-6/28/2006	110 Greenwich Street (roof level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	27	No	No	
PM10-ST13-6/28/2006	Marriott Hotel, 38th Floor (roof level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	18	No	No	
PM10-ST14-6/28/2006	West Face - South end at corner (scaffolding level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	15	No	No	
PM10-ST15-6/28/2006	South Face - East end at corner (scaffolding level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST16-6/28/2006	East Face - North end at corner (scaffolding level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	16	No	No	
PM10-ST17-6/28/2006	North Face - West end at corner (scaffolding level)	6/28/06	1440	Particulate	Direct Read	Met One E-BAM	20	No	No	
PM10-ST1-6/29/2006	Southwest Area (sidewalk bridge level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	39	No	No	
PM10-ST2-6/29/2006	Southeast Area (sidewalk bridge level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	59	No	No	
PM10-ST4-6/29/2006	Northwest Area (street-level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST10-6/29/2006	North Side Sidewalk Bridge	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	41	No	No	
PM10-ST100-6/29/2006	Station 10 Field Duplicate	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	44	No	No	
PM10-ST11-6/29/2006	90 Trinity Place (roof level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST12-6/29/2006	110 Greenwich Street (roof level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	38	No	No	
PM10-ST13-6/29/2006	Marriott Hotel, 38th Floor (roof level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	35	No	No	
PM10-ST14-6/29/2006	West Face - South end at corner (scaffolding level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST15-6/29/2006	South Face - East end at corner (scaffolding level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	
PM10-ST16-6/29/2006	East Face - North end at corner (scaffolding level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	32	No	No	
PM10-ST17-6/29/2006	North Face - West end at corner (scaffolding level)	6/29/06	1440	Particulate	Direct Read	Met One E-BAM	37	No	No	

Note:

1. The PM 10 reading at Station 5 (Firehouse #10 [roof level]) on June 29, 2006 was not available on account of instrument malfunction.