


REVISIONS		
NO.	DATE	DESCRIPTION
1	5-15-72	REVISED AS SHOWN
2	7-10-72	REVISED AS SHOWN
3	8-1-72	REVISED AS SHOWN
4	10-2-72	REAR COLI ADDED BEAMS NEAR COLI CT AS PER SEIL. DATE 10-2-72
5	10-15-72	ADDED 2" DIA. BEAMS NEAR COLI CT AS PER SEIL. DATE 10-15-72
6	12-15-72	ADDED 2" DIA. BEAMS NEAR COLI CT AS PER SEIL. DATE 12-15-72



NOTES:
1. REAR COLI TO BE 2" DIA. CONC. FULL ORN.
2. TOP OF CONC. SLAB 150' FROM TOP OF BEAM.
3. TOP OF BEAM 150' FROM TOP OF BEAM.
4. TOP OF BEAM 150' FROM TOP OF BEAM.
5. TOP OF BEAM 150' FROM TOP OF BEAM.
6. TOP OF BEAM 150' FROM TOP OF BEAM.
7. TOP OF BEAM 150' FROM TOP OF BEAM.

37TH FLOOR FRAMING
PLAN
37TH FLOOR
PROJECT NUMBER
7101
DRAWING NUMBER
S-25
DATE
SCALE

BANKERS TRUST
PLAZA
A FISHER BROTHERS
PROJECT
GREENWICH AND LIBERTY ST. N.Y. N.Y.
SHREVE LAMB HARMON ASSOCIATES PC
ARCHITECTS
475 PARK AVENUE SOUTH N.Y. N.Y. 10006
PETERSON AND BRICKBAUER
ASSOCIATED ARCHITECTS
919 THIRD AVENUE N.Y. N.Y. 10022
THE OFFICE OF JAMES RUDERMAN
STRUCTURAL ENGINEERS
335 MADISON AVENUE N.Y. N.Y. 10022
J. A. R. O. S. BAUM & BOLLIES
MECHANICAL ENGINEERS
345 PARK AVENUE N.Y. N.Y. 10022