

TRC Field Sample No.	Sample No.	Sampling Location	Collection Start Date	Work Shift	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Asbestos AHERA Concentration (S/mm2)	Exceeds Target	Exceeds EPA	Comments
Target Air Quality Levels										NA	Air Quality	Exceeds EPA	Comments
EPA Site Specific Trigger Levels										70	Levels	Trigger Levels	
ASBESTOS-ST1-8/2/07	030726230-0001	Southwest Area (sidewalk bridge level)	8/2/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST2-8/2/07	030726230-0002	Southeast Area (sidewalk bridge level)	8/2/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST4-8/2/07	030726230-0003	Northwest Area (street-level)	8/2/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST5-8/2/07	030726230-0004	Firehouse #10 (roof level)	8/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST10-8/2/07	030726230-0005	North Side Sidewalk Bridge	8/2/07	1	3.280	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST11-8/2/07	030726230-0006	90 Trinity Place (roof level)	8/2/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST12-8/2/07	030726230-0007	110 Greenwich Street (roof level)	8/2/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST13-8/2/07	030726230-0008	Marriott Hotel, 38th Floor (roof level)	8/2/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST14-8/2/07	030726230-0009	West Face - South end at corner (scaffolding level)	8/2/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST15-8/2/07	030726230-0010	South Face - East end at corner (scaffolding level)	8/2/07	1	3.100	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST16-8/2/07	030726230-0011	East Face - North end at corner (scaffolding level)	8/2/07	1	2.930	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST17-8/2/07	030726230-0012	North Face - West end at corner (scaffolding level)	8/2/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/3/07	< 13.00	No	No	
ASBESTOS-ST1-8/3/07	030726379-0001	Southwest Area (sidewalk bridge level)	8/3/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST2-8/3/07	030726379-0002	Southeast Area (sidewalk bridge level)	8/3/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST4-8/3/07	030726379-0003	Northwest Area (street-level)	8/3/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST5-8/3/07	030726379-0004	Firehouse #10 (roof level)	8/3/07	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST10-8/3/07	030726379-0005	North Side Sidewalk Bridge	8/3/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST11-8/3/07	030726379-0006	90 Trinity Place (roof level)	8/3/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST12-8/3/07	030726379-0007	110 Greenwich Street (roof level)	8/3/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST13-8/3/07	030726379-0008	Marriott Hotel, 38th Floor (roof level)	8/3/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST14-8/3/07	030726379-0009	West Face - South end at corner (scaffolding level)	8/3/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST15-8/3/07	030726379-0010	South Face - East end at corner (scaffolding level)	8/3/07	1	3.070	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST16-8/3/07	030726379-0011	East Face - North end at corner (scaffolding level)	8/3/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST17-8/3/07	030726379-0012	North Face - West end at corner (scaffolding level)	8/3/07	1	2.920	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/4/07	< 13.00	No	No	
ASBESTOS-ST1-8/4/07	030726564-0001	Southwest Area (sidewalk bridge level)	8/4/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST2-8/4/07	030726564-0002	Southeast Area (sidewalk bridge level)	8/4/07	1	2.950	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST4-8/4/07	030726564-0003	Northwest Area (street-level)	8/4/07	1	2.990	Asbestos	SEM	EMSL	8/6/07	< 4.63	No	No	
ASBESTOS-ST5-8/4/07	030726564-0004	Firehouse #10 (roof level)	8/4/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST10-8/4/07	030726564-0005	North Side Sidewalk Bridge	8/4/07	1	2.900	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST11-8/4/07	030726564-0006	90 Trinity Place (roof level)	8/4/07	1	2.970	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST12-8/4/07	030726564-0007	110 Greenwich Street (roof level)	8/4/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST13-8/4/07	030726564-0008	Marriott Hotel, 38th Floor (roof level)	8/4/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST14-8/4/07	030726564-0009	West Face - South end at corner (scaffolding level)	8/4/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST15-8/4/07	030726564-0010	South Face - East end at corner (scaffolding level)	8/4/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST16-8/4/07	030726564-0011	East Face - North end at corner (scaffolding level)	8/4/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST17-8/4/07	030726564-0012	North Face - West end at corner (scaffolding level)	8/4/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST1-8/5/07	030726562-0001	Southwest Area (sidewalk bridge level)	8/5/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST2-8/5/07	030726562-0002	Southeast Area (sidewalk bridge level)	8/5/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST4-8/5/07	030726562-0003	Northwest Area (street-level)	8/5/07	1	3.150	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 15.00	No	No	
ASBESTOS-ST5-8/5/07	030726562-0004	Firehouse #10 (roof level)	8/5/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST10-8/5/07	030726562-0005	North Side Sidewalk Bridge	8/5/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST11-8/5/07	030726562-0006	90 Trinity Place (roof level)	8/5/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 15.00	No	No	
ASBESTOS-ST12-8/5/07	030726562-0007	110 Greenwich Street (roof level)	8/5/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 15.00	No	No	
ASBESTOS-ST13-8/5/07	030726562-0008	Marriott Hotel, 38th Floor (roof level)	8/5/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST14-8/5/07	030726562-0009	West Face - South end at corner (scaffolding level)	8/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST15-8/5/07	030726562-0010	South Face - East end at corner (scaffolding level)	8/5/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST16-8/5/07	030726562-0011	East Face - North end at corner (scaffolding level)	8/5/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 13.00	No	No	
ASBESTOS-ST17-8/5/07	030726562-0012	North Face - West end at corner (scaffolding level)	8/5/07	1	3.110	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/6/07	< 15.00	No	No	
ASBESTOS-ST1-8/6/07	030726712-0001	Southwest Area (sidewalk bridge level)	8/6/07	1	3.230	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST2-8/6/07	030726712-0002	Southeast Area (sidewalk bridge level)	8/6/07	1	3.030	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST4-8/6/07	030726712-0003	Northwest Area (street-level)	8/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST5-8/6/07	030726712-0004	Firehouse #10 (roof level)	8/6/07	1	3.090	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST10-8/6/07	030726712-0005	North Side Sidewalk Bridge	8/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST11-8/6/07	030726712-0006	90 Trinity Place (roof level)	8/6/07	1	3.040	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST12-8/6/07	030726712-0007	110 Greenwich Street (roof level)	8/6/07	1	3.060	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST13-8/6/07	030726712-0008	Marriott Hotel, 38th Floor (roof level)	8/6/07	1	2.960	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST14-8/6/07	030726712-0009	West Face - South end at corner (scaffolding level)	8/6/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST15-8/6/07	030726712-0010	South Face - East end at corner (scaffolding level)	8/6/07	1	3.020	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST16-8/6/07	030726712-0011	East Face - North end at corner (scaffolding level)	8/6/07	1	3.050	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	
ASBESTOS-ST17-8/6/07	030726712-0012	North Face - West end at corner (scaffolding level)	8/6/07	1	3.010	Asbestos	TEM EPA 40 CFR PART 763 (AHERA)	EMSL	8/7/07	< 13.00	No	No	