| TRC Field Sample No.         | Sample No.     | Sampling Location          | Collection Start Date | Sample Volume (m <sup>3</sup> ) | Analyte | <b>Analytical Method</b> | Lab | Lab Sample Receipt Date | Dioxin TEQ Concentration (pg/m3) | Exceeds Target | Exceeds EPA |  |
|------------------------------|----------------|----------------------------|-----------------------|---------------------------------|---------|--------------------------|-----|-------------------------|----------------------------------|----------------|-------------|--|
|                              | 0.25           | Air Quality                | Site Specific         | Comments                        |         |                          |     |                         |                                  |                |             |  |
|                              | 25             | Levels                     | Trigger Levels        |                                 |         |                          |     |                         |                                  |                |             |  |
| Dioxins/Furans-ST10-6/19/06  | P6752_4147_006 | North Side Sidewalk Bridge | 6/19/06               | 349                             | Dioxin  | TO-9A                    | AP  | 6/21/06                 | 0.0396                           | No             | No          |  |
| Dioxins/Furans-ST100-6/19/06 | P6752_4147_014 | Station 10 Field Duplicate | 6/19/06               | 336                             | Dioxin  | TO-9A                    | AP  | 6/21/06                 | 0.0369                           | No             | No          |  |