TRC Field Sample No.	Sample No.	Sampling Location	<b>Collection Start Date</b>	Sample Volume (m <sup>3</sup> )	Analyte	Analytical Method	Lab	Lab Sample Receipt Date	Dioxin TEQ Concentration (pg/m3)	Exceeds Target	Exceeds EPA	
Target Air Quality Levels									0.25	Air Quality	Site Specific	Comments
	25	Levels	Trigger Levels									
Dioxins/Furans-ST2-7/5/06	P6812_4186_003CU	Southeast Area (sidewalk bridge level)	7/5/06	355	Dioxin	TO-9A	AP	7/7/06	0.0194	No	No	
Dioxins/Furans-ST10-7/5/06	P6812_4186_006	North Side Sidewalk Bridge	7/5/06	353	Dioxin	TO-9A	AP	7/7/06	0.0228	No	No	
Dioxins/Furans-ST100-7/5/06	P6812_4186_014	Station 10 Field Duplicate	7/5/06	340	Dioxin	TO-9A	AP	7/7/06	0.0254	No	No	